

TO ROUTINE TEST JACK ON RACK

TO SELECTOR OR RELAY SET UNDER TEST


NOTE
ALL WIRING TO BE 23 SWG UNLESS OTHERWISE STATED

BATT Bx SCA10 --- R4b R5b R6b K7b R5b R3b K2b
ETH R SCA11 --- R4a R3a KEB5 KEQ2

WIRING SIDE GUIDE

1	3	2	4
5	7	6	8
9	11	10	12
13	15	14	16
17	19	18	20
21	23	22	24

BPO 2403 PLUG



KESI 3 NUMBERING AND KES4 WAS SPARE KRS3 & 4 ADD (122096)	5	19	10	73	GFE
PLUG POINTS 14 & 16 REVERSED (GG016)	4	18	11	55	
N°2 & 2B CORDS DELETED	3	10	8		
ROUTING & DESIGNATION AMENDMENTS	2	14	4		
AMENDMENT PARTICULARS	1				
SS E DATE					
NZPO					

ROUTINE TEST SET
20 & 35/49 LINE
P A B X
SIZE 5
GBW 13290

5 Centimetres 10 15 20 25 30