AS SEEN FROM REAR



FIG 1A 9 SECS DELAY

AS SEEN FROM REAR



FIG 1B 20 SECS DELAY

AS SEEN FROM REAR



FIG 1C 30 SECS DELAY

AS SEEN FROM REAR



FIG 1D 3 MINS DELAY

AS SEEN FROM REAR



FIG 1E 6 MINS DELAY

NOTES

1. JACKS PTS U9 & U11 MAKE CONTACT WHEN RELAY SET IS REMOVED.
2. ALL WIRING TO BE 0·7mm. UNLESS OTHERWISE SPECIFIED.
3. ON 6 MINS ALARM DELAY RELAY SETS REMOVE ST WIRE MARKED ⊣× FROM U8 AND CONNECT WIRE MARKED ----.

AMENDMENT PARTICULARS		ISSUE	DATE	APPD
AMENDED TO NZMXI	(42327)	2B	7·12·83	GCG
RETRACED & METRICATED	(157660)	2A	14·6·78	R.E.D
CONNECTIONS TO U7 ADDED	(86675)	2	28·3·68	
——	(31667)	1	5·5·54	

ALARM DELAY RELAY SET 2000 TYPE

50V E

DRAWN CHECKED WIRING ENGINRS

GBU 11290

0 5 Centimetres 10 15 20 25 30 35 40